



To: Transfusion Services Managers
From: Hospital Relations Department
Date: November 24, 2021
Re: UPDATE_Pipette Calibration and Preventative Maintenance

UPDATE

Pipette calibration services have successfully relocated to the Bedford location; however, due to unforeseen equipment validation issues, pipette calibration services are temporarily unavailable. The service is expected to resume in early December 2021.

Background

Effective Monday November 8, 2021, all requests for pipette calibration services will be handled and processed by the Reference and Transfusion Department at the North Texas location in Bedford.

When shipping pipettes for service, please send to:

Carter BloodCare
Attention: Reference and Transfusion Services
2205 Hwy 121
Bedford, TX 76021

Please refer to the attached updated forms for pipette calibration and preventative maintenance. Additionally, these forms are located online via iWeBB® or on our specialty services website at <https://www.cbcspecialtyservices.org/download-forms>.